

Annexure G: Other information
Appendix G1: Coordinates of R335

1 Km Units	Description of land parcel	Start Coordinates 1 km Units	
		South	East
163.7	<ul style="list-style-type: none"> Vegetation: CBA Corridor 1 Addo Small airfield to the West 	32°44'28.14"S	25°35'53.99"E
163	<ul style="list-style-type: none"> Vegetation: CBA Corridor 1 Addo Informal settlement to the East Small airfield to the West 	32°44'43.68"S	25°35'53.70"E
162	<ul style="list-style-type: none"> Vegetation: CBA Corridor 1 Addo Informal settlement to the East Small airfield to the West 	32°45'15.99"S	25°35'53.21"E
161	<ul style="list-style-type: none"> Small airfield to the West 	32°45'48.30"S	25°35'55.56"E
160	<ul style="list-style-type: none"> Small dam to the West Farm access Farmhouse with additional building structures 	32°46'20.47"S	25°35'59.29"E
159	<ul style="list-style-type: none"> Cultivated land to the East, close to R335 Irrigated land to the immediate West of R335 	32°46'53.81"S	25°36'2.83"E
158	<ul style="list-style-type: none"> Large dam to the East Unused water canal 	32°47'25.69"S	25°36'6.21"E
157	<ul style="list-style-type: none"> Borrow pit to the East Canal crossing road 	32°47'57.71"S	25°36'4.86"E
156	<ul style="list-style-type: none"> Vegetation: CBA river corridor Addo Dam to the West Water course East to R335 Wetland on the East and West of the R335 Culvert crossing 	32°48'29.66"S	25°35'59.28"E
155	<ul style="list-style-type: none"> Farm accesses East and West of R335 large dam to the East Irrigated farmlands Culvert crossing 	32°49'0.04"S	25°35'48.50"E
154	<ul style="list-style-type: none"> Cultivated lands to the East and West, close to R335 with farm structure to the West Farm access Culvert crossing Dam and river to the East 	32°49'26.24"S	25°35'26.03"E
153	<ul style="list-style-type: none"> Small borrow pit to the West Large box culvert crossing- very well defined water course Large borrow pit not rehabilitated Farmhouse and building structures to the immediate East off R335 	32°49'55.90"S	25°35'16.60"E
152	<ul style="list-style-type: none"> Large quarry Borrow pit Canal crossing road Completed vegetated borrow pit Box culvert and significant water course crossing 	32°50'29.57"S	25°35'21.19"E
151	<ul style="list-style-type: none"> Vegetation: CBA river corridor Addo Culvert crossing Large box culvert 	32°51'1.75"S	25°35'21.79"E
150	<ul style="list-style-type: none"> Water course Farm access road to the East 	32°51'32.79"S	25°35'16.37"E
149	<ul style="list-style-type: none"> Farmhouse and building structures to the east of R335 Farm access roads Small canal crossing road Low level bridge and river crossing road Borrow pit to the West Water course parallel to the R335 	32°52'4.64"S	25°35'24.09"E
148	<ul style="list-style-type: none"> Vegetation: CBA river corridor Addo Low level bridge Two water courses 	32°52'24.31"S	25°35'0.45"E

	<ul style="list-style-type: none"> • Farmhouse/buildings to the East of R335 • Cultivated and irrigated farmlands off the R335 		
147	<ul style="list-style-type: none"> • Water course • Wetland area to the West 	32°52'55.58"S	25°34'45.84"E
146	<ul style="list-style-type: none"> • Seven water courses • Dam wall to the East 	32°53'22.89"S	25°34'37.38"E
145	<ul style="list-style-type: none"> • Water course 	32°53'30.16"S	25°34'5.30"E
144	<ul style="list-style-type: none"> • Vegetation: CBA T3 (Vulnerable) Corridor • Farm buildings off the R335 NW of the CBA and farmland off the CBA in the SE direction • Erosion East and West • River • Quarry being worked 	32°53'36.23"S	25°33'29.49"E
143	<ul style="list-style-type: none"> • Vegetation: CBA T3 (Vulnerable) Corridor • Two water courses • Borrow Pit 450/13 • Farm access 	32°53'51.35"S	25°32'59.88"E
142	<ul style="list-style-type: none"> • Vegetation: CBA T3 (Vulnerable) Corridor • Three water courses 	32°54'17.86"S	25°32'43.07"E
141	<ul style="list-style-type: none"> • Vegetation: CBA river corridor Addo • Six water courses • Farm access 	32°54'49.63"S	25°32'37.65"E
140	<ul style="list-style-type: none"> • Vegetation: CBA river corridor Addo • Large erosion scar to the immediate West 	32°55'19.88"S	25°32'24.22"E
139	<ul style="list-style-type: none"> • Water course • Large box culvert • Water crossing • Power line crossing • Road junction • Narrow road 	32°55'51.83"S	25°32'23.94"E
138	<ul style="list-style-type: none"> • Two water courses running perpendicular to R335 	32°56'23.99"S	25°32'28.30"E
137	<ul style="list-style-type: none"> • Seven water courses • Water course crossing • Vegetation: CBA river corridor Addo 	32°56'56.19"S	25°32'32.74"E
136	<ul style="list-style-type: none"> • Vegetation: CBA river corridor Addo • Three water courses running perpendicular to R335 • Small old borrow pit the West • Erosion scar to the West of R335 	32°57'26.97"S	25°32'46.53"E
135	<ul style="list-style-type: none"> • Vegetation: CBA river corridor Addo • Vegetation: CBA river corridor • Erosion on either side of R335 	32°57'56.48"S	25°33'0.47"E
134	<ul style="list-style-type: none"> • Vegetation: CBA river corridor Addo • Three water courses • Large borrow pit 	32°58'17.07"S	25°33'18.72"E

133	<ul style="list-style-type: none"> • Vegetation: CBA river corridor Addo • Three water courses running perpendicular to R335 • Low level crossing (drift) • Farm access East and West • Farm homestead with various building structures • Culvert crossing the farm access • Dam to the West 	32°58'45.61"S	25°33'35.00"E
132	<ul style="list-style-type: none"> • Vegetation: CBA river corridor Addo • Water course: running NE/SW • Borrow Pit BR4 • Small dam on right of Modderfontein 	32°59'16.38"S	25°33'46.40"E
131	<ul style="list-style-type: none"> • Vegetation: CBA river corridor Addo • Eskom power line crossing • Borrow pit to the West 	32°59'46.30"S	25°34'2.85"E
130	<ul style="list-style-type: none"> • Vegetation: CBA river corridor Addo • Low level bridge with span of approx. 3m • Farm to the East 	33° 0'14.44"S	25°34'20.95"E
129	<ul style="list-style-type: none"> • Vegetation: CBA river corridor Addo • Culvert crossing • Dam over grown by trees and bushes 	33° 0'45.49"S	25°34'32.16"E
128	<ul style="list-style-type: none"> • Vegetation: CBA river corridor Addo • Small water course, small pipe 	33° 1'15.05"S	25°34'44.55"E
127	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Vegetation: CBA river corridor Addo • Canal crossing the road right after power line crossing 	33° 1'42.67"S	25°35'3.31"E
126	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Vegetation: CBA river corridor Addo • Cattle grids on both sides of the road • Narrow bridge • Stone wall • Cultivated land to the East and West 	33° 2'11.32"S	25°35'18.88"E
125	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Borrow Pit BR2 • Canal crossing 	33° 2'41.85"S	25°35'31.48"E
124	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Fence reserves are wide (approx. 30m) • Furrows next to the road and culvert crossings • Trig beacon East of road 	33° 3'11.95"S	25°35'45.40"E
123	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Fence reserves narrow considerably 	33° 3'43.21"S	25°35'55.19"E
122	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Large earth canal • Water course with possible wetlands to the West • Access roads and gates either side on the south side of the canal • Wetland either side of the road with culvert crossing • Large concrete canal crossing the road 	33° 4'15.05"S	25°36'1.86"E

121	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Vegetation: CBA river corridor Addo • Wetland on East and West side • Fence on the West side is close to the irrigation canal • Farmstead with a few building structures • Cultivated lands to the West and East 	33° 4'45.96"S	25°36'12.35"E
120	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Vegetation: CBA river corridor Addo • Intersection to the West has a little island and a slip way coming from south to the left • Fence about 7m off the road • Wetland 	33° 5'16.21"S	25°36'26.03"E
119	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) 	33° 5'49.12"S	25°36'45.86"E
118	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Fence on East side far back, fence on West side about 2m from edge of the road 	33° 6'16.19"S	25°36'55.41"E
117	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Erosion West and East of the R335 	33° 6'46.45"S	25°37'10.78"E
116	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Old borrow pits East and West sides, largely vegetated • Small dam 	33° 7'17.47"S	25°37'21.32"E
115	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Old borrow pit • Farmhouse to the East approximately 0.15 km's off the R335 • Some cultivated lands to the immediate West of the R335 	33° 7'45.08"S	25°37'35.74"E
114	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Vegetation: CBA T2 (Endangered) corridor • Fence to the east is much closer to the road than the fence to the West 	33° 8'10.52"S	25°37'59.00"E
113	<ul style="list-style-type: none"> • Vegetation: CBA corridor 2 (catchments) • Small dam to the West • Small culvert crossing 	33° 8'34.35"S	25°38'22.77"E
112	<ul style="list-style-type: none"> • Historical stone wall to the East 	33° 8'43.50"S	25°38'59.60"E
111	<ul style="list-style-type: none"> • Culvert crossing • Historical stone wall to the East • Culvert crossing 	33° 8'52.81"S	25°39'36.38"E
110	<ul style="list-style-type: none"> • Water crossing with erosion to the West 	33° 9'3.67"S	25°40'12.36"E
109	<ul style="list-style-type: none"> • Water course with erosion on either side of the road • Farm access to the East 	33° 9'18.26"S	25°40'41.46"E
108	<ul style="list-style-type: none"> • Vegetation: CBA River corridor Addo • Borrow Pit BR1 • Large dam to the West • Water crossing 	33° 9'44.07"S	25°41'2.77"E
107	<ul style="list-style-type: none"> • Vegetation: CBA River corridor Addo • Farm access road to the East 	33°10'8.00"S	25°41'28.42"E
106	<ul style="list-style-type: none"> • Vegetation: CBA River Corridor Addo • Small cultivated lands to the West 	33°10'33.99"S	25°41'51.16"E

	<ul style="list-style-type: none"> • Small dam to the West 		
105	<ul style="list-style-type: none"> • Concrete structure to the East, possible erosion protection • Large storm water crossing • Large dam • Low density residential • Crossing culvert and old borrow pit to the East • Bracefield school • Small homesteads 	33°11'2.95"S	25°41'54.77"E
104	<ul style="list-style-type: none"> • Large box culvert crossing, just after Bracefield • R400 intersecting with R335, heading East • Small homesteads with medium sized dam to the West 	33°11'27.64"S	25°42'18.58"E
103	<ul style="list-style-type: none"> • Possible unused borrow pit or dry dam • Farm entrance to the West 	33°11'49.97"S	25°42'47.65"E
102	<ul style="list-style-type: none"> • Farm entrances to the East and West • Farmhouse to the West is close to the R335, approximately 0.2 km's off the R335 • Some minor cultivated land 	33°12'12.24"S	25°43'15.58"E
101	<ul style="list-style-type: none"> • Small dam to the East 	33°12'34.73"S	25°43'43.70"E
100	<ul style="list-style-type: none"> • Waterway to the East 	33°12'57.02"S	25°44'11.75"E
99	<ul style="list-style-type: none"> • Vegetation: CBA River Corridor Addo • Farm entrance to the West • Farmhouse approximately 0.8 km's along farm entrance • A few light industrial buildings are present 	33°13'10.55"S	25°44'44.53"E
98	<ul style="list-style-type: none"> • Vegetation: CBA River Corridor Addo • Borrow Pit AV6 • Farm entrance to the West • Farmhouse approximately 2.3 km's along farm entrance 	33°13'34.37"S	25°45'11.30"E
97	<ul style="list-style-type: none"> • Vegetation: CBA T2 (Endangered) corridor 	33°13'54.80"S	25°45'38.67"E
96	<ul style="list-style-type: none"> • Vegetation: CBA T2 (Endangered) corridor • Flat semi-arid lands 	33°14'7.98"S	25°46'13.48"E
95	<ul style="list-style-type: none"> • Vegetation: CBA T2 (Endangered) corridor • Borrow Pit AV5 • Farmhouse with small cultivated section of land • Sheds with light industrial structures 	33°14'35.16"S	25°46'20.08"E
94	<ul style="list-style-type: none"> • Vegetation: CBA T3 (Vulnerable) Corridor • Borrow Pit 450/3 • Farmhouse 	33°15'7.13"S	25°46'19.61"E
93	<ul style="list-style-type: none"> • Borrow Pit AV4 • Anne's Villa B & B - historical significance • Graveyard a few meters off the R335 	33°15'23.74"S	25°46'49.98"E
92	<ul style="list-style-type: none"> • Vegetation: CBA River corridor Addo • Narrow section of the R335 	33°15'35.91"S	25°46'31.56"E
91	<ul style="list-style-type: none"> • Steep gradient through the Zuurberg pass • Narrow section of the R335 	33°16'2.26"S	25°46'10.89"E
90	<ul style="list-style-type: none"> • Vegetation: CBA River corridor Addo • Vegetation: CBA Corridor 1 Addo • End of the denser vegetation to more semi-arid conditions 	33°16'21.73"S	25°46'36.28"E
89	<ul style="list-style-type: none"> • Steep gradients with narrow road • Historical homesteads approximately 50 meters of 	33°16'27.61"S	25°46'0.11"E

	the R335		
88	<ul style="list-style-type: none">• Borrow pit 450/1• Steep gradients with narrow road• Vegetation is denser through the pass than the northern section	33°16'45.35"S	25°45'29.71"E